

<u>Field Resistor</u>	<u>Resistance</u>	<u>Field Resistor</u>	<u>Resistance</u>
Resistor 137a	910 ohms	Resistor 137ab	110000 ohms
Resistor 137b	3830 ohms	Resistor 137ac	113000 ohms
Resistor 137c	5490 ohms	Resistor 137ad	121000 ohms
Resistor 137d	7150 ohms	Resistor 137ae	127000 ohms
Resistor 137e	15000 ohms	Resistor 137af	130000 ohms
Resistor 137f	15800 ohms	Resistor 137ag	137000 ohms
Resistor 137g	18200 ohms	Resistor 137ah	147000 ohms
Resistor 137h	30100 ohms	Resistor 137ai	150000 ohms
Resistor 137i	31600 ohms	Resistor 137aj	158000 ohms
Resistor 137j	36500 ohms	Resistor 137ak	165000 ohms
Resistor 137l	38300 ohms	Resistor 137al	169000 ohms
Resistor 137l	44200 ohms	Resistor 137am	174000 ohms
Resistor 137m	51000 ohms	Resistor 137an	182000 ohms
Resistor 137n	51100 ohms	Resistor 137ao	187000 ohms
Resistor 137o	53600 ohms	Resistor 137ap	191000 ohms
Resistor 137p	54900 ohms	Resistor 137aq	196000 ohms
Resistor 137q	56200 ohms	Resistor 137ar	200000 ohms
Resistor 137r	61900 ohms	Resistor 137as	205000 ohms
Resistor 137s	66500 ohms	Resistor 137at	210000 ohms
Resistor 137t	698 00 ohms	Resistor 137au	221000 ohms
Resistor 137u	71500 ohms	Resistor 137av	232000 ohms
Resistor 137v	73200 ohms	Resistor 137aw	243000 ohms
Resistor 137w	82500 ohms	Resistor 137ax	249000 ohms
Resistor 137x	88700 ohms	Resistor 137ay	470000 ohms
Resistor 137y	90900 ohms	Resistor 137az	680000 ohms
Resistor 137z	93100 ohms	Resistor 137ba	910000 ohms
Resistor 137aa	100000 ohms	Resistor 137bb	1M ohms

Table 1

2/3




Fig. 1

3/3




Fig. 2